

Assembly / Bridge non-handed (23 1/2"D x 23 1/2"W x 29 1/2"H,600Dx600Wx750H)

1

Diagram 1 shows the preparation of the worksurface panel and modesty panel. The worksurface panel has two connectors (B) being attached to its bottom edge. The modesty panel has a cam (A) and a grommet (C) being attached to its top edge, and two glides (D) and two dowels (E) being attached to its bottom edge.

worksurface panel

modesty panel

Hardware for step 1:

- A*2 (Cam)
- C*1 (Grommet)
- D*2 (Glide)
- E*2 (Dowel)
- B*2 (Connector)

2

Diagram 2 shows the bridge being attached to the worksurface panel. The bridge is being placed on top of the worksurface panel, and the cam lid (F) is being attached to the bridge. The bridge is being attached to the worksurface panel using four mending plates (G).

finished product

bridge must be attached to freestanding furniture with mending plates

Hardware for step 2:

- F*2 (Cam lid(deep))
- G*4 (Mending plate (include screws))
- C*1 (Grommet)

Hardware			
NO.	sample.pc	name	QTY
A		Cam	2
B		Connector	2
C		Grommet	2
D		Glide	2
E		Dowel	2
F		Cam lid(deep)	2
I		Mending plate (include screws)	4